

**Barn Close Playground
Quarndon**

Original equipment inspection


	Risk level			Comment	Action
	Low	Med	High		
Entrance sign	✓			In good order.	
Entrance litter bin	✓			In good order.	
Entrance bike rack	✓			All okay.	
Sign at swings	✓			Sign in place.	
Seat	✓			Fully re-furbished.	
Ground borders	✓			Drainage channels working. Field very dry and just droplets of water from pipe.	
Fencing	✓			Fencing in good order. Field secure.	
Field condition	✓			Field freshly cut, ground very dry and firm. Trees planted 2-3 years ago growing well. Plastic tube supports could now be removed.	
Swing surfacings	✓			In good order. Very little moss or detritus.	
2-bay swing, open seats	✓			Swings moving freely, no issues. All bird spikes in place.	
2-bay swing, closed seats	✓			Swings moving freely, no issues. All bird spikes in place.	
Large goal post	✓			No problems. More movement in very dry ground. Slight forward lean but no issue.	
Climbing frame	✓			No problems.	
Basket ball hoop	✓			No problems. Still fairly clean.	

**Barn Close Playground
Quarndon**

New equipment inspection

	Risk level			Comment	Action
	Low	Med	High		
1 Ladder walk	✓			Very solid. Good surfacing.	
2 Parallel bars	✓			Very solid. Good surfacing.	
3 Twin balance beam	✓			Very solid. Good surfacing. Dry and usable.	
4 Step-ups	✓			Very solid. Posts have vertical splits, but not a safety issue.	
5 Chin-ups	✓			Very solid. Good surfacing.	
Trim trail seat	✓			Very solid.	
Trim trail signage	✓			Very solid.	
5-a-side posts	✓			No issues. All looks good.	
Seesaw horse	✓			Very solid. Pivoting smoothly. Good surfacing.	
East side bench table	✓			Very solid. Surfaces dry and clean.	
West side bench table	✓			Some movement in seating planks. Surfaces dry but very grubby/green.	
Willow tunnel	✓			No sign of damage/vandalism. Trimming completed.	
Wigloo	✓			No sign of damage/vandalism. Trimming completed.	

Signed: Kevin Sawley



Date: 30 Aug 2024

Time: 11:00

Weather: Dry, sunny, very warm.